





МОЛЛИС




COMFORT PLUS
НОВАЯ ФОРМУЛА КОМФОРТА




**4,5x40
x12**



**M6x60
x4**




**M10x95
x2**




**M10x50
x4**





**M8
x8**



**кM10
x2**



**шайба из фанеры
x2**



M6x60

x1

4,5x40


x3

x2


Diagram illustrating the assembly of the top plate and side panels:

- Top Plate:** A rectangular plate with 6 holes (3 on each long side). It is secured to the side panel with **M6x60** screws. **x1** (one screw per side panel).
- Side Panel:** A rectangular panel with 4 holes (2 on each long side). It is secured to the top plate with **4,5x40** screws. **x3** (three screws per side panel).
- Side Panel:** A rectangular panel with 2 holes (1 on each long side). It is secured to the top plate with **4,5x40** screws. **x2** (two screws per side panel).



3



4



M10x50





M10




x2

5



6



7

